

MULTIPLE DWELLING INSPECTION REPORT

SEQUENCE #: 00974

Page ____ of ____

DORM C

- ⇒ Room 6: Heater not Functioning
- ⇒ Room 12: No Smoke Alarm.
- ⇒ Room 13: No Smoke Alarm.

Dorm D

- ⇒ Room 7: Heater not Functioning

Dorm E

- ⇒ Room 15: Heater not Functioning
- ⇒ Room 11: No electric outlet.

BANE 17

Men's Room D

- ⇒ electric outlet does not Function

Dorm F

- ⇒ Room 13: Heater Does not Function.
- ⇒ Room 3: Heater not Functioning
- ⇒ Room 23: Heater not Functioning
- ⇒ Room 26: Heater not Functioning
- ⇒ Room 22: Heater not Functioning
- ⇒ Room 22: electric outlet not Functioning.

Dorm H

- ⇒ Room 6: Heater and Smoke Alarm not Functioning
- ⇒ Room 10: No Smoke Alarm
- ⇒ Room 20: Holes in Ceiling,

Toaster present in Room, heater not Functioning

Dorm G

- ⇒ Room 5: No Smoke Alarm

Dorm I

- ⇒ Room 6: No Smoke Alarm.

MULTIPLE DWELLING INSPECTION REPORT

SEQUENCE #: 00974

Page ____ of ____

Dorm C:

Ladies restroom: ok

Rm #3: ok

Rm #8: ok

Rm #10:

• Non. functioning heating unit

Rm #15: ok

Dorm D:

Rm #8: Non functioning heating unit

Rm #10: ok

Rm #2: • smoke alarm removed

Rm #4: • heater not used

Dorm E:

Room #5: ok

Room #16: heat not functioning

Room #12: • unauthorized cooking
apparatus
• heat not functioning

Ladies lounge: ok

Dorm F:

Rm #14: • heat not functioning

Rm #10: • needs smoke alarm
• heat not functioning

Rm #5:

• Missing smoke alarm

• Heat not functioning

~~Rm #14~~

Rm #28: • Heat not functioning

Rm #27: • Heat not functioning

Rm #24: ok

Rm #21: ok

Dorm H:

Rm #3: ok

Rm #5: • unsanitary cond. on ceiling
• heat not functioning

Rm #15: ok

Rm #18: ok

Rm #19: ok

Rm #22: ok

Dorm G:

Rm #18: • no heating unit
present
• detached smoke alarm

Rm #18: ok

Dorm I:

Rm #4: ok

MULTIPLE DWELLING INSPECTION REPORT

SEQUENCE #: 00974

Page ____ of ____

Bldg. C:

Ladies bathroom - all ok
unit #3 - 11ft x 12.3ft x
7ft (height)

20in. x 28in.
window

Bldg. D:

unit #9 - inoperable heater
unit #1 - inoperable heater

Bldg. E:

unit #2 - no smoke alarm
unit #18 - inoperable heater

Bldg. F:

unit #15 - inoperable heater
unit #32 - inoperable heater
unit #25 - no smoke alarm
unit #18 - no smoke alarm

Bldg. H:

unit #9 - inoperable heater
unit #14 - no smoke alarm

Bldg. I:

unit #5 - 9ft. 10in x
11ft 3in.
8ft. (height)

45in x 55in
(window)

• Ladies Lounge - all ok

• Kitchen/Restaurant -
all ok

• common area - all ok

MULTIPLE DWELLING INSPECTION REPORT

SEQUENCE #: 00974

Page ____ of ____

Dorm C:

Unit # 6

- Heater non-functional

Unit # 11

- cooking equipment

Dorm D:

Unit # 11

- Heater non-functional

Unit # 12

- Heater non-functional

Dorm E:

Unit # 9

- unsanitary conditions

Dorm F:

Unit # 1

- non-functional smoke alarm

Unit # 11

- non-functional Heater

Unit # 30

- cooking equipment

Unit # 23

- No smoke alarm

Dorm H:

Unit # 2

- No smoke alarm

Unit # 7

- Cracking / Damage along front ceiling

Unit # 12

- Heater non-functional

- cooking equipment

Dorm G:

Unit # 1

- No smoke alarm

- Heater non-functional

Unit # 3

- No batteries in smoke alarm

- Heater non-functional

Dorm G Room # 18:

Damaged smoke alarm



Missing heating unit



Dorm E: # 12 Unauthorized cooking apparatus



Dorm H: #5

Water damage to ceiling



Dorm
H
Room
20



Dorm
H
Room
20



Dorm
F
Room
22






Dorm H: Unit 12 – Cooking Equipment (Toaster)



Dorm H: Unit #7 – Crack/Damage along front ceiling



Dorm F: Unit #30 – Cooking Equipment (Microwave)



Dorm E: Unit #9 – Unsanitary Conditions



Dorm C: Unit #11 – Cooking Equipment (Slow Cooker)